



xylem
Let's Solve Water

YSI incorporated

1700/1725 Brannum Lane
Yellow Springs OH 45387 USA
tel: 937-767-7241 • fax: 937-767-9353

SonTek
San Diego, CA

Packing List

Page 1 of 3

Delivery Number	Packing Slip Number	Date Shipped
852358	YSI-269387	07-FEB-12
Shipped Via: FEDEX-Truck-Ground		

CERTIFICATE OF COMPLIANCE

This is to certify that the materials, processes and finished products were controlled, tested, and accepted in accordance with our quality system and the applicable specifications.

Ron Geis
Vice President & General Manager

SOLD TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

SHIP TO

NATIONAL PARK SERVICE
3100 NATIONAL PARK RD
JUNEAU, AK 99801, United States

PICKUP DATE	PAYMENT TERMS	FREIGHT TERMS	SR NUMBER	F.O.B	TAX NAME	TAX NO.	Supplier No.
07-FEB-12	Credit Card	Prepaid	290853	Shipping Point	Exempt		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
10.1	R6150	639153		CREDITCA RD		Repair, Model 6150 Model: 6150 SN: 11E101714 Reported Symptom: P.M. All O-rings and quad seal replaced with new due to P.M. Probe was final tested. Probe read 100% in air saturated bath. Meets YSI specs.	9801.10.0000	EA	1	1	0
12.1	R6920V2	639153		CREDITCA RD		Repair, Model 6920V2 Model: 6920V2 SN: 08H100353 Reported Symptom: P.M. All O-rings replaced with new due to P.M. PH probe needs replaced with new. Customer didn't want ph probe replaced. Sonde was pressure tested. Temp read 21.6 in a 21.7 controlled bath. Cond cal constant 4.84732, 0 us/cm in air. Batt voltage 4.3V. Batteries need replaced with new before next deployment. Meets YSI specs.	9801.10.0000	EA	1	1	0
14.1	R6150	639153		CREDITCA RD		Repair, Model 6150 Model: 6150 SN: 08H101103	9801.10.0000	EA	1	1	0

-For terms and conditions refer to WWW.YSI.COM/TERMS_CONDITIONS

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



xylem

Let's Solve Water

YSI incorporated

1700/1725 Brannum Lane
Yellow Springs OH 45387 USA
tel: 937-767-7241 • fax: 937-767-9353

SonTek
San Diego, CA

Packing List

Page 2 of 3

Delivery Number	Packing Slip Number	Date Shipped
852358	YSI-269387	07-FEB-12
Shipped Via: FEDEX-Truck-Ground		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						Reported Symptom: P.M. All O-rings and quad seal replaced with new due to P.M. Probe was final tested. Probe read 100% in air saturated bath. Meets YSI specs.					
2.1	R6920V2	639153		CREDITCARD		Repair, Model 6920V2 Model: 6920V2 SN: 08H100355 Reported Symptom: P.M. All O-rings replaced with new due to P.M. PH probe needs replaced with new. Customer didn't want to replace ph probe. Sonde was pressure tested. Temp read 21.6 in a 21.5 controlled bath. Cond cal constant 4.86122, 0 us/cm in air. Batt Voltage was 7.5V. Batteries need to be replaced before next deployment. Meets YSI specs.	9801.10.0000	EA	1	1	0
4.1	R6136	639153		CREDITCARD		Repair, Model 6136 Model: 6136 SN: 10C101561 Reported Symptom: P.M. All O-rings and quad seal replaced with new. Probe was final tested. Probe read 112.5 NTU in standard. Meets YSI specs.	9801.10.0000	EA	1	1	0
6.1	R6150	639153		CREDITCARD		Repair, Model 6150 Model: 6150 SN: 08H101102 Reported Symptom: P.M. All O-rings and quad seal replaced with new. Probe was final tested. Probe read 100% in air saturated bath. Meets YSI specs.	9801.10.0000	EA	1	1	0
8.1	R6920V2	639153		CREDITCARD		Repair, Model 6920V2 Model: 6920V2 SN: 08H100354 Reported Symptom: P.M. All O-rings replaced with new due to P.M. PH probe needs replaced with new. Customer didn't want to replace ph probe. Sonde was pressure tested. Temp read 21.7 in a 21.7 controlled bath. Cond cal constant 4.80554, 0 us/cm in air. Batt Voltage 5V. Batteries need to be	9801.10.0000	EA	1	1	0

-For terms and conditions refer to WWW.YSI.COM/TERMS_CONDITIONS

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.



xylem

Let's Solve Water

YSI incorporated

1700/1725 Brannum Lane
Yellow Springs OH 45387 USA
tel: 937-767-7241 • fax: 937-767-9353

SonTek
San Diego, CA

Packing List

Page 3 of 3

Delivery Number	Packing Slip Number	Date Shipped
852358	YSI-269387	07-FEB-12
Shipped Via: FEDEX-Truck-Ground		

ORDER LINE NO.	YSI ITEM NO.	ORDER NO.	CUSTOMER ITEM NO.	PO NO.	PO Line#	DESCRIPTION	HS NO.	UOM	QTY ORDERED	QTY SHIPPED	BACK ORDERED
						replaced with new before next deployment. Meets YSI specs.					
GROSS WEIGHT(LB) :		21.55	NET WEIGHT (LB) :		21.55	VOLUME(CC) :	0	TOTAL CARTONS: 0			
ADDITIONAL INFO:		045403060046675									
ADDITIONAL NOTE:											

Tracking Number: 

0 4 5 4 0 3 0 6 0 0 4 6 6 7 5

-For terms and conditions refer to WWW.YSI.COM/TERMS_CONDITIONS

-These commodities, technology or software were exported from the United States in accordance with the Export Administration Regulations. Diversion contrary to U.S. law is prohibited.

Sonde Instrument Number (I.N)

6920V2-01

NOTE: An * (asterisk) following the Sonde IN indicates the Sonde settings were not properly verified when added


START TEST

STOP TEST

Test Status

Standby


PSI applied Measured PSI



Results

Sonde SN

08H100353



Sonde Instrument Number (I.N)

6920V2-01

NOTE: An * (asterisk) following the Sonde IN indicates the Sonde settings were not properly verified when added


START TEST

STOP TEST

Test Status

Standby


PSI applied Measured PSI



Results

Sonde SN

08H100355



Sonde Instrument Number (I.N)

6920V2-01

NOTE: An * (asterisk) following the Sonde IN indicates the Sonde settings were not properly verified when added

START TEST

STOP TEST

Test Status

Standby

PSI applied Measured PSI



Results

Sonde SN

08H100354

